


South 1 Elevation Material Percentages

Material	Percentage
Glazing	32.6%
Stone Veneer	33.4%
CMU Block	2.5%
CFB Panel	16.9%
Board and Batton	5.0%
Lap Siding	9.6%



STANDING SEAM METAL ROOFING

CULTURED STONE VENEER

FIBER CEMENT PANEL - Color 2

SCREEN DECK

FIBER CEMENT BOARD AND BATTON SIDING - Color 1

FIBER CEMENT LAP SIDING - Color 3




① Elevation - South 1
1/16" = 1'-0"

East Elevation Material Percentages

Material	Percentage
Glazing	19.0%
Stone Veneer	26.2%
CMU Block	4.9%
CFB Panel	32.6%
Board and Batten	3.4%
Lap Siding	13.9%

West Elevation Material Percentages

Material	Percentage
Glazing	17.5%
Stone Veneer	24.2%
CMU Block	12.1%
CFB Panel	30.1%
Board and Batten	3.2%
Lap Siding	12.9%



① Elevation - East
1/16" = 1'-0"




② Elevation - West
1/16" = 1'-0"

Exterior Elevations

Zvago Canterbury Crossing


North Elevation Material Percentages

Material	Percentage
Glazing	30.3%
Stone Veneer	30.9%
CMU Block	2.4%
CFB Panel	14.4%
Board and Batton	1.8%
Lap Siding	20.2%



North 2 Elevation Material Percentages


Material	Percentage
Glazing	27.6%
Stone Veneer	24.2%
CMU Block	7.8%
CFB Panel	16.5%
Board and Batton	2.6%
Lap Siding	21.1%



① Elevation - North 2
1/16" = 1'-0"

South 2 Elevation Material Percentages

Material	Percentage
Glazing	27.4%
Stone Veneer	26.1%
CMU Block	8.1%
CFB Panel	16.9%
Board and Batton	1.6%
Lap Siding	19.9%



① Elevation - South 2
1/16" = 1'-0"









