

Platte Valley Construction

ESTIMATE

Customer Name _____ Date: 5-20-18
Project Address 100 South Fuller Street

Job Description	Cost
Tear out Existing Concrete and Flagstone	900-
Remove Existing Stump	600-
Pour New Concrete inside Courtyard with 2 Steps	4,100-
Color Group 1 Ton	600-
If necessary Shorten Retaining Wall for Equipment	? 500-
Total Estimated Cost	